Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

 GU976
 MANHOLE 71178
 NY Spills
 S103829535

 West
 NEPTUNE AVE/W 37TH ST
 N/A

> 1 BROOKLYN, NY

1.291 mi.

6816 ft. Site 1 of 5 in cluster GU

Relative: SPILLS:
Higher Name: MANHOLE 71178

Actual: Address: NEPTUNE AVE/W 37TH ST

0 ft. City,State,Zip: BROOKLYN, NY Spill Number/Closed Date: 9815446 / 1999-03-31

9815446 Facility ID: Facility Type: ER DER Facility ID: 81471 Site ID: 89151 DEC Region: 2 Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date:

 Spill Date:
 1999-03-29

 Investigator:
 CAENGELH

 Referred To:
 Not reported

 Reported to Dept:
 1999-03-29

 CID:
 252

Water Affected:
Spill Source:
Spill Notifier:
Cleanup Ceased:
Cleanup Meets Std:
Cleanup Meets Std:
Cleanup Water Affected Persons
Not reported
False

Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 1999-03-29
Spill Record Last Update: 2000-06-19
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN

Spiller Company: 999

Contact Name: STEPHEN CRIBBINS

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

ENGELHARDT CON ED E2MIS NOTES Undiaperable sheen found on 400 gals.

of water, contained. No sewers or waterways affected. 1 sample taken on 4-6 hr priority, tag #13600 placed 3-29-99 18:35 Lab Seq# 00-03183 <1.0ppm PCB 3-30-99 1330 Cleanup complete, tag remove. Incident

closed."

Remarks: "UNK OIL NOTICED FROM SHEEN ON WATER IN MANHOLE-HAS BEEN CONTAINED

CON ED#123929."

All Materials:

 Site ID:
 89151

 Operable Unit ID:
 1076468

 Operable Unit:
 01

 Material ID:
 308552

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G

Map ID		MAP FINDINGS		
Direction		4		
Distance				EDR ID Number
Elevation	Site		Database(s)	EPA ID Number

Recovered: .00

Oxygenate: Not reported